

Accumulated sand and grit cleaned from aeration basin and digester while plant remains online

BRANFORD, FLORIDA

PROBLEM

The Town of Branford, FL, was experiencing loss of detention volume and reduced water quality as a result of accumulated sand and grit on the bottom of their aeration basin and digester. The roughly 200,000 gallon per day facility had a large quantity of sand submerged under water. The accumulated sand and grit had reduced the efficiency of the grit chamber and was potentially exposing other elements in the treatment system to a buildup of sediments and particulates.

SOLUTION

Using the 949 Combination³® Truck and the GritGone ProcessSM, we pulled more than 35 cubic yards of accumulated material (sand and grit) from the bottom of their wastewater treatment plant - without taking the system offline! By removing the sand, the Town of Branford facility realized a significant effective increase in capacity (volume).



RESULTS

The USST crew provided a sustainable solution that reduces energy costs, reuses wastewater and generates a waste product that can be economically disposed of in a landfill.



U.S. SUBMERGENT
TECHNOLOGIES

www.usubmergent.com
844-765-7866
235 N. Orange Ave, St 201
Sarasota, FL 34236